

1: Correct because clear 36" path between all furniture elements and between furniture and walls to access all seats.

3: Wrong because 36" should be provided to gain access to the SE chair. The NE chair blocks this path. Could work if table was nudged N to provide 36" between wall and seat edge.

5: Correct because there is a clear 36" path to each seat. 36" between furniture elements.

2: Wrong because 36" between furniture elements was not provided (chair & book shelves)

4: Correct because there is a clear 36" path to each seat. NOTE the similarity to #2. But 36" must be provided between two furniture elements &/or between table edge and wall. Same goes for the executive desk configurations when adjacent to a credenza element.

6: Correct because 36" clear between two furniture elements which provides access to the S chair. S edge of table is 36" clear to wall.